




## HEADBOARD SET ASSEMBLY INSTRUCTION (TOTAL 1 BOX)




A x 1 pc



B x 1 pc




C x 2 pcs



D x 4 pcs



E x 2 pcs



F x 1 pc

Please read over the instructions, it will be a time-saver in the long run.

Note: Before assembly, please be sure to work on a soft flat surface to avoid any damage to the finish.

Please leave bolts loosened until all bolts are placed before tightening completely.

| Part# | Picture | Description               | QTY | Location               | Part# | Picture | Description          | QTY | Location         |
|-------|---------|---------------------------|-----|------------------------|-------|---------|----------------------|-----|------------------|
| G     |         | Center leg                | 1   | Spare Parts cation box | R     |         | Spring Washer Ø8     | 20  | Hardware Pack    |
| H     |         | Triangle connection piece | 2   | Spare Parts cation box |       |         |                      | 16  | Already in Place |
| I     |         | Legs                      | 4   | Spare Parts cation box | S     |         | Flat Washer Ø8x25mm  | 20  | Hardware Pack    |
| J     |         | Bolt Ø6x30mm              | 6   | Already in Place       |       |         |                      | 16  | Already in Place |
| K     |         | Bolt Ø8x30mm              | 16  | Already in Place       | T     |         | Spring Washer Ø6     | 6   | Already in Place |
| L     |         | Bolt Ø8x60mm              | 16  | Hardware Pack          | U     |         | Flat Washer Ø6x25mm  | 6   | Already in Place |
| M     |         | Bolt Ø8x70mm              | 2   | Hardware Pack          | V     |         | Spring Washer Ø10    | 2   | Hardware Pack    |
| N     |         | "L" Wrenches Ø4           | 1   | Hardware Pack          | W     |         | Flat Washer Ø10x25mm | 2   | Hardware Pack    |
| O     |         | "L" Wrenches Ø5           | 1   | Hardware Pack          | X     |         | Spanner Ø14          | 1   | Hardware Pack    |
| P     |         | Nut Ø8                    | 2   | Hardware Pack          | Y     |         | Spanner Ø17          | 1   | Hardware Pack    |
| Q     |         | Nut Ø10                   | 2   | Hardware Pack          | Z     |         | Screws 4x30mm        | 24  | Hardware Pack    |

